

State of Utah DEPARTMENT OF NATURAL RESOURCES Division of Oil, Gas & Mining

MICHAEL R. STYLER Executive Director JOHN R. BAZA Division Director

Supervisor #

Inspection Report Minerals Regulatory Program

Report Date: June 27, 2005

Mine Name: Red Warrior	
Operator or Permittee Name:	

L & M Engineering & Construction, Inc.

Permit number: S/053/012 **Inspection Date:** June 21, 2005

E to 111 Engineering & Construction, me.

Weather: Hot, Windy

Inspector(s): Doug Jensen

Inspection Start Time: 2:00 PM
Inspection End Time: 2:45 PM

Other Participants: None

Elements of Inspection	Evaluated	N/A	Comment	Enforcement
1. Permits, Revisions, Transfer, Bonds				
2. Public Safety (open shafts, adits, trash,				
signs, highwalls)		Ш		Ш
3. Protection of Drainages				
4. Explosives, magazines				
5. Deleterious Material				
6. Roads (maintenance, surfacing, dust control,				
safety)				
7. Concurrent Reclamation				
8. Erosion Control				
9. Demolition				
10. Backfilling and Grading (trenches, pits,				
roads, highwalls, shafts, drill holes)				
11. Water Impoundments				
12. Soils				
13. Revegetation				
14. Air Quality				
15. Facilities				
16. Other: Public Complaint	\boxtimes			

Purpose of Inspection:

Received a report that this quarry was now active, after a long period of inactivity. Also checked out a public complaint that the operator's trucks were tearing up the access road into the site.

Inspection Summary:

There was no equipment around the quarry at the time of my visit. There was a pick-up parked in the quarry, but no sign of the owner.



Inspection Date: June 21, 2005; Report Date: June 27, 2005

Page 2 of 2 S/053/012

There has been quite a bit of material removed from the quarry since my last visit, but the footprint of the site has not expanded. Most of the loose material that existed at the quarry for some time had been removed. There is evidence that some drilling and blasting had taken place in portions of the quarry.

16. The quarry was left in a stable condition, with no environmental concerns. I could not see where the operation of the quarry had had any lasting effect on the access road.

Directions to the site:

See previous inspection memos.

Inspector's Signature

Date: June 27, 2005

DJ:jb

Enclosures: photos

cc: L&M Engineering & Construction, Operator

John Blake, SITLA

O:\M053-Washington\S0530012-RedWarrior\inspections\06212005insp.doc

